


**HCC SERVICE SINGLE
ARM COLUMN**



**HCC SERVICE SINGLE ARM
COLUMN WITH SUBFUSE**

NOTES:

1. Individually fused to BS88-2 suitable size to the loading and protection of the cable.
2. Extension box may be required to assist with termination of the cables.
3. Test tags to be fitted indicating month and year of test and next test due date.
4. Telenso 1 part 5 wire communication node (Programmed to Hertfordshire) OSID number (TELENSA on drawing) to be affixed to the isolator on the inside of the lantern and on the relevant paperwork.
5. Label locations shown are indicative only and subject to supply type characteristics.

Notes

A	Various drawing revisions	AS	RC	DOK	07/21
	Description	Dwn	Chk	App	Date

IWP No.	N/A			
	CAD	Drawn	Checked	Approved
Initials	PB	PB	ADS	PW
Date	04/10	04/10	04/10	04/10
Sht. No.	1 OF 1			
Scales	NTS			

Drg No.	HST-1400-005		Rev.	A
Project Title				
HCC STANDARD DETAIL DRAWINGS				
Drawing Title				
SINGLE ARM COLUMN TERMINATION HCC SUPPLY				

COUNTY HALL
Pegs Lane
Hertford, Herts
SG13 8DN
Phone: 01992 555555