


PTRO Review

Type: Byway Open to All Traffic


Name: Great Munden 028

Location: Great Munden

Location map



Route map path condition.



Effectiveness of the existing order
Constant use by cycle/equine. Some evidence of motorbike use – minimal.

Public safety issues
Mostly good but potential for horse and motorbike conflict.
Physical evidence of level of use
Good for current use levels.
Surface condition
Ruts in places, muddy at times, generally good.
Improvement suggestions
Horse stile is beginning to corrode, ruts could be infilled.
Structures & Signs
Orange end PTRO sign not apparent & therefore not enforceable, (photo 1)
Comments
Parish comments desire PTRO to remain.

J Bartlett
RoW Enforcement Officer
Aug 2020